

## Installation & Operation Manual L Bracket Work Surface

**The purpose of this guide is to:**

- Describe installation of the Work Surface to the L-Bracket.

**Tools Required:**

- Phillips Screwdriver (not provided)

**Parts Reference:**

Description	QTY
Work Surface	1
10-32 x 7/16" FHMS	3
Work Surface Recess Label	1

